

General Equipment Info

Year

Make

Komatsu

Model

PC290LC-10

Hours

6,256

Serial Number

KMTPc241L54A25719

Machine Options

Cab, Heat, Aux. Hydraulics, Ripper, Digging Bucket, Cleanup Bucket

Address

City

Langley

Province/State

Bc

Inspector Name

Flori

Date of Inspection

02-06-2024

Hour Meter - Idle Hours



Serial Number Plate




Hour Meter - SMU Hours



Dimensions

Measurement Guide



A. Length (ft and inches)

27'

B. Width (ft and inches)

11' 11/2"

C. Height (ft and inches)

12'6"

D. Shipping Width (ft and inches)

11' 11/2"

Operational Weight (lbs)

Exterior Condition

Coupler Style

Pin Grabber

Coupler Brand

Coupler Width (Between bucket ears)

Stick Width (Between bucket ears)

14 3/8"

Pin Size

3 1/8"

Center to Center of Bucket Pins

Excavator Boom Length

Exterior Walkaround Photos

Loader Bucket Pin Height

Width Between Bucket Ears

Top Pin Size

Bottom Pin Size

Center to Center of Coupler Pins



Coupler Photos



Hard Bar Photos

Close-up Exterior Photos



Chassis Photos



Undercarriage Condition

Undercarriage Type

Tracks

Tire Size

Tire Brand

Front Left Tire - Ratio Remaining

Rear Left Tire - Ratio Remaining

Front Right Tire - Ratio Remaining

Rear Right Tire - Ratio Remaining

Wheel and Tire Condition

Left Track - Ratio Remaining

70%

Right Track - Ratio Remaining

70%

Track Condition

Good condition, wear consistent with hours

Front Left Tire - Photos

Rear Left Tire - Photos


Front Right Tire - Photos

Rear Right Tire - Photos

Left Track - Photos

Pad Width Instructions


Take photo of tape measure on pad/grousers



Right Track - Photos



Pad Width Photo



Interior Condition

Interior Condition

Engine Condition

Engine Info

Gather general engine information if available (i.e., Make, Model, Cylinders, type, Horsepower).

Emissions Tier

Engine Serial Number

73563104

Unusual Noises (Upon Start-up, Idle, Shutdown)

Engine Exhaust Color

Engine Compartment Photos

Engine Type (Make, Model, Cylinders, HP)

Komatsu

Blow-by (Visual Observation Check)


Engine Smoke (Upon Start-up, Idle, Shutdown)




Active Engine Codes

A/C Compressor

Engine Data Plate



EPA Label



Hydraulic System

Hydraulic Pumps / Motors Condition

Unable to test

Hydraulic Lines/Fittings Condition

Unable to test

Hydraulic Cylinders Condition

Unable to test

Hydraulic Cylinder Photos



Hydraulic System Photos



Hydraulic Leaks Photos

Drivetrain

Hydrostatic Transmission?

2 Speed?

Drive

Transmission Condition

Axle Condition

Drivetrain Photos

Parking Brake Function

Function Check

Hydraulic Operation

1

Service Brakes Operation

1

Electronics Operation

1

Forward / Reverse

1

Attachment Operation

1

Park Brake Operation

1

Attachments

Attachment Type

Clean out bucket

Attachment Make

Daequip

Attachment Size / Specs

Attachment Serial Number

Attachment Photos



Attachment Serial Number Photo

Attachment Width Photo

