

General Equipment Info

Year

2019

Make

Komatsu

Model

D65PXI-18

Hours

1

Serial Number

KMT0D127PJA091476

Machine Options

Cab, Heat, A/C, 6-Way Blade, Ripper

Address

(52.7828169, -112.7767845)

City

Edburg

Province/State

AB

Inspector Name

Adam Dow

Date of Inspection

03-13-2024

Hour Meter - Idle Hours

Serial Number Plate




Hour Meter - SMU Hours





Dimensions

Measurement Guide



A. Length (ft and inches)

23' 4"

B. Width (ft and inches)

11' 11"

C. Height (ft and inches)

11' 9"

D. Shipping Width (ft and inches)

12' 6"

Operational Weight (lbs)

Exterior Condition

Coupler Style

Exterior Walkaround Photos



Coupler Brand

Coupler Width (Between bucket ears)

Stick Width (Between bucket ears)

Pin Size

Center to Center of Bucket Pins

Excavator Boom Length

Loader Bucket Pin Height

Width Between Bucket Ears

Top Pin Size

Bottom Pin Size

Center to Center of Coupler Pins

















Coupler Photos

Hard Bar Photos

Close-up Exterior Photos







































Chassis Photos





Undercarriage Condition



Tracks **Tire Size**

Tire Brand

Front Left Tire - Ratio Remaining

Rear Left Tire - Ratio Remaining

Front Right Tire - Ratio Remaining

Rear Right Tire - Ratio Remaining

Wheel and Tire Condition

Left Track - Ratio Remaining 30%

Right Track - Ratio Remaining

Track Condition

Good condition, wear consistent with hours

Pad Width Instructions


Take photo of tape measure on pad/grousers

Rear Left Tire - Photos

Front Right Tire - Photos

Rear Right Tire - Photos

Left Track - Photos















Right Track - Photos





Pad Width Photo







Interior Condition


Interior Condition





















Engine Condition

Engine Info

Gather general engine information if available (i.e., Make, Model, Cylinders, type, Horsepower).

Emissions Tier

Engine Serial Number

Unusual Noises (Upon Start-up, Idle, Shutdown)

Engine Exhaust Color


Engine Type (Make, Model, Cylinders, HP)

Blow-by (Visual Observation Check)

Engine Smoke (Upon Start-up, Idle, Shutdown)

Engine Compartment Photos




















Active Engine Codes


A/C Compressor

Engine Data Plate





EPA Label







Hydraulic System

Hydraulic Pumps / Motors Condition

Hydraulic Lines/Fittings Condition

Hydraulic Cylinders Condition

Unable to test

Hydraulic Cylinder Photos

















Hydraulic System Photos Hydraulic Leaks Photos

Drivetrain

Hydrostatic Transmission?

Yes

Drivetrain Photos



2 Speed?

Yes

Drive

Transmission Condition

Unable to test

Axle Condition

Unable to test

Parking Brake Function

Unable to test





Function Check

Hydraulic Operation

1

Service Brakes Operation

1

Electronics Operation

1

Forward / Reverse

1

Attachment Operation

Park Brake Operation

1

Attachments

Attachment Type

Ripper

Attachment Make

Komatsu

Attachment Size / Specs

Three shank

Attachment Serial Number

2093

Attachment Photos









Attachment Serial Number Photo





Attachment Width Photo



